Inspection Report

Provided by:



Kyle's Home Inspections

Inspector: Kyle Salony
Certified & Insured
NACHI23041008
ICA Certification # 31527
Cell Number - (760) 881-7036
Website - kyleshomeinspections.com

Property Address 1234 Sample Ave Murrieta ca 92563



Table Of Contents:

Section name:	Page number
---------------	-------------

Report Information	
Report Summary Page	6
Grounds	10
Exterior	13
Roofing	19
Heating - Air	27
Electrical	33
Plumbing	36
Living Room	41
Kitchen	45
Bedroom(s)	50
Bath(s)	57
Garage - Laundry	63
Foundation - Crawl Space	
Hallway	
Stairs	69

Report Information

Client Information

Client Name John Doe

Client Phone 951-000-0000

Property Information

Approximate Year Built 2004

Approximate Square Footage 3,000

Number of Bedroom 5.

Number of Bath 3.

Inspection Information

Inspection Date 01-18-25

Inspection Time 10:30am

Weather Conditions Clear

Outside Temperature 60

Price for Inspection \$499

- 4. Scope of Inspection. The scope of the inspection is strictly limited as set forth in this Agreement. The parties understand and agree that this inspection will be of readily accessible areas of the building and is limited to visual observations of apparent conditions existing at the time of the inspection only. Latent and concealed defects and deficiencies, including but not limited to, basement flooding, basement seepage and roof leakage, are excluded from this inspection. The parties agree that the American Society of Home Inspectorsâ (ASHIâ) Standards of Practice, most current edition, shall define the standard of duty and the conditions, limitations, and exclusions of the inspection and are incorporated by reference herein. Copies of these standards are available upon request.
- 5. Items Not Inspected. The inspection and report exclude and do not cover those items indicated as "untested" or "not inspected" or the possible presence of or danger from any potentially harmful substances and environmental hazards including, but not limited to, the following items: asbestos; lead paint; formaldehyde; toxic and flammable materials; soil contamination; water testing; termite and pest infestation; water softener and filter system; sprinkler systems; central vacuum systems; telephone systems; intercom systems; security systems; antennas; cable television; doorbells; appliances; playground equipment; swimming pools and pool equipment; spas; energy efficiency measurements; recreational equipment; recreational facilities (boat docks and tennis courts); landscaping; underground storage tanks; underground drainage; irrigation; outdoor grills; low voltage exterior lighting; remote overhead door transmitters and receivers; concealed or underground electric and plumbing; systems which are shut down or otherwise secured; private sewer systems; water wells; chimney draft; heating

system accessories; solar heating systems; zoning or other ordinances; and building code conformity. All items indicated as being excluded in the ASHIâ Standards of Practice are also excluded herein. CLIENT understands that these systems and conditions and information about them are excluded from this Inspection and Report. Any general comments which may appear about these systems and conditions are provided as a courtesy only and DO NOT represent or form a part of the Inspection.

- 6. Third Party Liability. It is understood and agreed that the inspection and report are performed and prepared for the confidential and exclusive use and possession of CLIENT. No other person or entity may rely on the report issued pursuant to this agreement.
- 7. Limitation of Liability. It is understood and agreed that in the event of any claim whatsoever against COMPANY, it's employees, inspectors, or other agents, whether based on contract, negligence or other tort, statute, or otherwise, in any way directly or indirectly resulting from or relating to the inspection, the report or performance or nonperformance of services by COMPANY, that, any liability of COMPANY, it's employees, inspectors or other agents shall be solely and exclusively limited to the amount of the inspection fee actually paid by CLIENT.
- 8. Limitation of Actions. No action shall be maintained by CLIENT against COMPANY unless written notice, sent by certified mail return receipt requested, setting forth that an installed system or component of the Premises which was inspected by the Inspector was not in the condition reported by the Inspector, is delivered by CLIENT to COMPANY within ten (10) business days after the discovery of such defect becomes known to CLIENT. CLIENT agrees that, with the exception of emergency conditions, CLIENT or CLIENT'S agents, employees or independent contractors will make no alterations, modifications or repairs to the claimed discrepancy prior to a reinspection by the Inspector. Furthermore, any action must be commenced by CLIENT within one (1) year after the date of the Inspection or will be deemed waived and forever barred.
- 9. Entire Agreement. This Agreement constitutes the entire Agreement between the parties and supersedes any and all prior agreements between the parties. CLIENT agrees that any representation, promise, condition, or warranty, express or implied, not included in this Agreement shall not be binding on any party.
- 10. Interpretations. It is mutually understood and agreed that all provisions herein are severable and that, in the event that any of them shall be held to be invalid, any competent court may modify or reform any such provisions to make it enforceable and that the remaining provisions hereof shall nevertheless be valid and binding.
- 11. Assignment. The rights and obligations under this Agreement may not be assigned by any of the parties hereto without the prior written consent of the other party.
- 12. Attorney's Fees. The prevailing party in any dispute arising out of this Agreement, the Inspection, or Report(s) shall be awarded reasonable attorney's fees and other costs.

Definition of conditions:

AS = Appears Serviceable: The item appeared to be in working or usable condition with no major discrepancies noted.

- R = Repair: The item was at or near the end of its useful lifespan. A certified professional should be contacted for further evaluation and repair.
- **S** = Safety Issue: The item is considered a safety hazard and can cause harm to people or property. These items need to be repaired as soon as possible.

NI = Not Inspected: The item was not inspected during the inspection.

Report Summary Page

This is only a summary of the inspection report and is not a complete list of discrepancies.

Grounds

1.4 Conditions (Repair)

Backyard side fence was falling down. It is suggested that a "Licensed Fencing Contractor" be contacted for further evaluation and repair.

Exterior

2.1 Front Entrance Conditions (Repair)

Front rock features had a loose part. Recommend securing it back on.

2.3 Exterior Wall Conditions (Repair)

One small section near Backdoor had broken stucco. Recommend sealing as needed.

2.4 Window Conditions (Repair)

The seals inside the window panes are popping out on multiple windows. Backyard 2nd floor window has broken window trim. It is suggested that a "Licensed window Contractor" be contacted for further evaluation and repair.

2.6 Faucet Conditions (Repair)

Front & backyard faucet handle leaked. It is suggested that a "Licensed Plumbing Contractor" be contacted for further evaluation and repair.

Roofing

3.1 Roof Covering Condition (Repair)

One slipped tile in front of home above garage.

3.2 Flashing Conditions (Repair)

Valleys in front of home had debris inside them. Recommend cleaning.

3.4 Attic Conditions (Repair)

2x4 was cut and damaged near entrance. One exhaust fan is slipping out and needs to be secured better to vent.

3.7 Conditions (Repair)

Front of home had gaps in the fascia boards on the corners. Splits in eaves. Recommend repairs as needed. It is suggested that a "Licensed Roofing Contractor" be contacted for further evaluation and repair.

Heating - Air

4.4 AC Unit Conditions (Repair)

The insulation on the refrigerant lines was missing or deteriorated. Recommend installing this rather inexpensive pipe insulation to improve efficiency. Pipe insulation is available at most hardware stores. Units are 20 years old and nearing the end of there lifespan.

Plumbing

6.2 Supply Line Conditions (Repair)

The visible portions of the supply lines had minor corrosion observed at the accessible areas.

6.3 Drain Line Conditions (Repair)

Upstairs master bath had flex plumbing. Recommended replacing with proper plumbing.

6.4 Water Heater Conditions (Repair)

Minor corrosion on water line. It is suggested that a "Licensed Plumbing Contractor" be contacted for further evaluation and repair.

Living Room

7.5 Interior Window Conditions (Repair)

2 windows has seals inside that coming out. It is suggested that a "Licensed window Contractor" be contacted for further evaluation and repair.

7.7 Electrical Conditions (Repair)

Open ground outlet near fire place. It is suggested that a "Licensed Electrical Contractor" be contacted for further evaluation and repair.

7.10 Fireplace Conditions (Safety)

Missing doors to fireplace and damper latch. It is suggested that a "Licensed chimney Contractor" be contacted for further evaluation and repair.

Kitchen

8.7 Electrical Conditions (Repair)

Kitchen island was off.

8.8 Lighting Conditions (Repair)

Light(s) were out or inoperative at underneath the cabinets. Dismantling and testing of all light fixtures is not performed as part of this inspection. Recommend all lights be operable prior to close.

8.10 Cabinet Conditions (Repair)

The cabinets were loose. Recommend securing or repair as needed for increased safety. One cabinet was stuck and would not operate.

8.11 Sink Plumbing Conditions (Safety)

Kitchen sink was leaking and water was running down the cords and Into the reciprocal underneath the sink. Unplugged dishwasher and garbage disposal. It is suggested that a "Licensed Plumbing Contractor" be contacted for further evaluation and repair.

8.12 Garbage Disposal Condition (Not Inspected)

Not inspected due to power being off to the kitchen island.

8.13 Stove - Range Condition (Not Inspected)

Not inspected due to being unplugged.

8.15 Dishwasher Conditions (Not Inspected)

Not inspected due to power being off at kitchen island. Dishwasher was not secured in place either.

Bedroom(s)

9.5 Interior Window Conditions (Safety)

Cracked glass pane(s) were observed at upstairs. Window mechanism is sticking out and doesn't function. Recommend repair as needed.

9.6 Interior Door Conditions (Repair)

Upstairs bedroom door doesn't latch properly. It is suggested that a "Certified Handy Man" be contacted for further evaluation and repair.

Bath(s)

10.11 Sink Conditions (Repair)

Downstairs restroom had a slow drain.

10.12 Shower - Tub Conditions (Repair)

Upstairs guest shower tub diverter was leaking and not functioning properly. Upstairs master stand up shower had a leak on the windows and should be sealed. It is suggested that a "Licensed Plumbing Contractor" be contacted for further evaluation and repair.

10.13 Toilet Conditions (Repair)

Upstairs guest bathrooms toilet continuously runs. It is suggested that a "Licensed Plumbing Contractor" be contacted for further evaluation and repair.

Garage - Laundry

11.1 Wall Conditions (Repair)

Suspicious growth near water heater.

11.2 Ceiling Conditions (Repair)

Some of the drywall edge is coming off as well as a suspicious spot in between the garage doors on the ceiling.

11.5 Vehicle Door Conditions (Repair)

No motor for single garage door.

1 Grounds

Grading

Grading Slope

The site is slightly sloped.

1.1) Grading Conditions



The visible areas of the sidewalk appeared to be in serviceable condition at the time of the inspection.







Driveways - Sidewalks - Walkways

Driveway Material Concrete.

1.2) Driveway Conditions AS

The driveway appeared to be in serviceable condition at the time of the inspection.

Sidewalk Material Concrete.

1.3) Sidewalk Conditions AS

The visible areas of the sidewalk appeared to be in serviceable condition at the time of the inspection.

Fencing

1.4) Conditions

Backyard side fence was falling down. It is suggested that a "Licensed Fencing Contractor" be contacted for further evaluation and repair.



2 Exterior

Front - Back Entrance

Front Entrance Type

Covered Porch.

2.1) Front Entrance Conditions



Front rock features had a loose part. Recommend securing it back on.



Back Entrance Type

Covered Patio.

2.2) Back Entrance Conditions



Appears Serviceable.



Exterior Walls

Structure Type

Exterior Wall Covering

Wood frame.

The visible and accessible areas of the exterior siding material are stucco.

2.3) Exterior Wall Conditions



One small section near Backdoor had broken stucco. Recommend sealing as needed.



Exterior Windows - Doors

Window Type Double Hung & Sliding.

Window Material Vinyl.

2.4) Window Conditions

The seals inside the window panes are popping out on multiple windows. Backyard 2nd floor window has broken window trim. It is suggested that a "Licensed window Contractor" be contacted for further evaluation and repair.







2.5) Exterior Door Conditions



The door(s) appeared to be in serviceable condition at the time of the inspection.

Exterior Water Faucet(s)

Faucet Location

Front and backyard

2.6) Faucet Conditions



Front & backyard faucet handle leaked. It is suggested that a "Licensed Plumbing Contractor" be contacted for further evaluation and repair.





Chimney

2.7) Chimney Conditions



The visible and accessible portions of the chimney(s) appeared to be in serviceable condition at the time of the inspection.

Soffits & Vents

2.8) Conditions



Appears Serviceable.



3 Roofing

Roof Covering

Method of Inspection

Used a camera attached to an extension pole.



Roof Style Hip & Valley

Roof Covering Material Concrete Tile

Number of Layers One.

3.1) Roof Covering Condition

One slipped tile in front of home above garage.
















3.2) Flashing Conditions

R

Valleys in front of home had debris inside them. Recommend cleaning.



3.3) Gutter & Downspout Conditions



The gutter system appeared to be in serviceable condition at the time of the inspection.

Attic Area

Attic Access The attic access was located at master bedroom closet

Method of Inspection The attic was inspected by partially entering due to

blocked access and / or personal item storage.

Roof Frame Type The roof framing is constructed with truss framing.





3.4) Attic Conditions



2x4 was cut and damaged near entrance. One exhaust fan is slipping out and needs to be secured better to vent.











Attic Ventilation Type

Soffit vents & Gable Vents.

3.5) Attic Ventilation Conditions



The ventilation in the attic appeared to be adequate.

Attic Insulation Type

Loose fill.

3.6) Attic Insulation Conditions



Appears Serviceable.





Fascia & Eaves

3.7) Conditions



Front of home had gaps in the fascia boards on the corners. Splits in eaves. Recommend repairs as needed. It is suggested that a "Licensed Roofing Contractor" be contacted for further evaluation and repair.









4 Heating - Air

Heating

Location of Unit Attic.

Heating Type Forced Air.

Energy Source Natural Gas.

4.1) Unit Conditions

AS

The heating system was operational at time of inspection. This is not an indication of future operation or condition.



Distribution Type

The visible areas of the heat distribution system is ductwork with registers.

4.2) Distribution Conditions



The visible and accessible areas of the distribution system appeared to be in serviceable condition at the time of inspection.














4.3) Ventilation Conditions



The visible and accessible portion of the venting flue appeared to be in serviceable condition at the time of the inspection.

Air Condition - Cooling

Type of Cooling System Forced air

4.4) AC Unit Conditions



The insulation on the refrigerant lines was missing or deteriorated. Recommend installing this rather inexpensive pipe insulation to improve efficiency. Pipe insulation is available at most hardware stores. Units are 20 years old and nearing the end of there lifespan.












4.5) Distribution Conditions



Appears Serviceable.







Return Filters

4.6) Conditions



Appears Serviceable.

Thermostat

4.7) Conditions



Appears Serviceable.

5 Electrical

Service Drop - Weatherhead

Electrical Service Type The electrical service is underground.

Electrical Service Material Copper.

Number of Conductors Two.

5.1) Electrical Service Conditions

AS

The main service entry appeared to be in serviceable condition at the time of inspection.



Main Electrical Panel

Main Disconnect Location At Main Panel.

Electric Panel Location The main electric panel is located at the exterior.

Panel Amperage Rating The electrical capacity of main breaker was listed / labeled

as 200 amps.

Circuit Protection Type Breakers.

5.2) Wiring Methods

Plastic insulated (romex) type wire is present.

5.3) Electrical Panel Conditions



The main panel appeared to be in serviceable condition at the time of the inspection.





Exterior Electrical

5.4) Fixtures Conditions

AS

Appears Serviceable.

5.5) Outlets-Switches Conditions



Appears Serviceable.





6 Plumbing

Water Main Line

Main Shutoff Location

The main valve is located at the exterior of the home.

Main Line Material

The visible material of the main line / pipe appears to be

copper.

6.1) Main Line & Valve Conditions



The visible portion of the main pipe and valve appeared to be in serviceable condition at the time of the inspection.





Water Supply Lines

Supply Line Material

The visible material used for the supply lines is copper.

6.2) Supply Line Conditions



The visible portions of the supply lines had minor corrosion observed at the accessible areas.





Drain - Waste Lines

Drain Line Material

The visible portions of the waste lines are plastic.

6.3) Drain Line Conditions



Upstairs master bath had flex plumbing. Recommended replacing with proper plumbing.









Water Heater(s)

Water Heater Type Natural Gas.

Water Heater Location Garage.

Water Heater Capacity 50 Gallon.

6.4) Water Heater Conditions



Minor corrosion on water line. It is suggested that a "Licensed Plumbing Contractor" be contacted for further evaluation and repair.


















7 Living Room

Walls - Ceilings - Floors

7.1) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.



7.2) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.

7.3) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.

7.4) HVAC Source Conditions



Appears Serviceable.

Windows - Doors

7.5) Interior Window Conditions



2 windows has seals inside that coming out. It is suggested that a "Licensed window Contractor" be contacted for further evaluation and repair.





7.6) Interior Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection.

Electrical Conditions

7.7) Electrical Conditions



Open ground outlet near fire place. It is suggested that a "Licensed Electrical Contractor" be contacted for further evaluation and repair.







7.8) Lighting Conditions

AS

Appears Serviceable.

7.9) Smoke Detector Conditions



Appears Serviceable.

Fireplace

Fireplace Location

A fireplace is located at the living room.

Fireplace materials


The fireplace is metal/pre-fabricated.

7.10) Fireplace Conditions

S

Missing doors to fireplace and damper latch. It is suggested that a "Licensed chimney Contractor" be contacted for further evaluation and repair.







8 Kitchen

Walls - Ceilings - Floors

8.1) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.



8.2) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.

8.3) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.

8.4) HVAC Source Conditions



Appears Serviceable.

Windows - Doors

8.5) Kitchen Window Conditions



Appears Serviceable.

8.6) Kitchen Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection.

Electrical Conditions

8.7) Electrical Conditions



Kitchen island was off.





8.8) Lighting Conditions



Light(s) were out or inoperative at underneath the cabinets. Dismantling and testing of all light fixtures is not performed as part of this inspection. Recommend all lights be operable prior to close.

Kitchen Sink - Counter tops - Cabinets

8.9) Counter Conditions



The visible portion kitchen counters appeared to be in serviceable condition at the time of the inspection.

8.10) Cabinet Conditions



The cabinets were loose. Recommend securing or repair as needed for increased safety. One cabinet was stuck and would not operate.



8.11) Sink Plumbing Conditions



Kitchen sink was leaking and water was running down the cords and Into the reciprocal underneath the sink. Unplugged dishwasher and garbage disposal. It is suggested that a "Licensed Plumbing Contractor" be contacted for further evaluation and repair.







8.12) Garbage Disposal Condition



Not inspected due to power being off to the kitchen island.

Appliances

Stove - Range Type

The oven is gas.

8.13) Stove - Range Condition



Not inspected due to being unplugged.



8.14) Hood Fan Conditions



Appears Serviceable.

8.15) Dishwasher Conditions



Not inspected due to power being off at kitchen island. Dishwasher was not secured in place either.



9 Bedroom(s)

Walls - Ceilings - Floors

9.1) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.











9.2) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.

9.3) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.

9.4) HVAC Source Conditions



Appears Serviceable.

Windows - Doors

9.5) Interior Window Conditions



Cracked glass pane(s) were observed at upstairs. Window mechanism is sticking out and doesn't function. Recommend repair as needed.



9.6) Interior Door Conditions



Upstairs bedroom door doesn't latch properly. It is suggested that a "Certified Handy Man" be contacted for further evaluation and repair.



Electrical Conditions

9.7) Electrical Conditions













9.8) Lighting Conditions

AS

Appears Serviceable.

9.9) Smoke Detector Conditions









Closets

9.10) Conditions









10 Bath(s)

Walls - Ceilings - Floors

10.1) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.







10.2) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.

10.3) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.

10.4) HVAC Source Conditions



Appears Serviceable.

Windows - Doors

10.5) Bathroom Window Conditions



Appears Serviceable.

10.6) Bathroom Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection.

Electrical Conditions

10.7) Electrical Conditions









10.8) Lighting Conditions

AS

Appears Serviceable.

10.9) Vent Fan Conditions

AS

Appears Serviceable.

Bathroom Sink

10.10) Counter - Cabinet Conditions



Appears Serviceable.

10.11) Sink Conditions



Downstairs restroom had a slow drain.



Shower - Tub - Toilet

10.12) Shower - Tub Conditions



Upstairs guest shower tub diverter was leaking and not functioning properly. Upstairs master stand up shower had a leak on the windows and should be sealed. It is suggested that a "Licensed Plumbing Contractor" be contacted for further evaluation and repair.







10.13) Toilet Conditions



Upstairs guest bathrooms toilet continuously runs. It is suggested that a "Licensed Plumbing Contractor" be contacted for further evaluation and repair.



11 Garage - Laundry

Walls - Ceilings - Floors

Garage Type

The garage is attached to the house.

11.1) Wall Conditions



Suspicious growth near water heater.





11.2) Ceiling Conditions



Some of the drywall edge is coming off as well as a suspicious spot in between the garage doors on the ceiling.





11.3) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.

11.4) Door Conditions



Appears Serviceable.

11.5) Vehicle Door Conditions



No motor for single garage door.



11.6) Electrical Conditions



Appears Serviceable.



11.7) Lighting Conditions



Appears Serviceable.

Laundry Room



Location

Off garage entrance

11.8) Laundry Room Conditions



There were no appliances present for proper testing of plumbing components.





12 Foundation - Crawl Space

Foundation

Foundation Type Slab on grade.

Foundation Material Concrete.

12.1) Foundation Conditions

AS

13 Hallway

Hallway Conditions

13.1) Conditions







14 Stairs

Stairs - Handrails

14.1) Conditions

